

Operating Instructions



Alu-Cleaner 101

General

For cleaning and pickling of aluminium prior or after welding and before painting. With Alu-Cleaner 101 the surfaces are perfectly clean and free of its oxide layer.

Application

Apply Alu-Cleaner 101 onto the surface by the hand sprayer. Allow the solution 2 - 3 min. to work in. This process may need to be repeated until the surface is bright and completely wetted. After this operation the parts must be rinsed with water.

Health and safety

Please note the hazard warnings on the product label and the separate safety data sheet.

Environmental protection

Used Alu-Cleaner 101 solutions must not be disposed of in drains without treatment.

Disclaimer

This issue replaces all previous issues. The information is provided to the best of our knowledge and conscience and conforms to the laboratory and field experience at the time of going to press. However, it must only be regarded as non-binding guidelines which have to be adapted to requirements. Since the use of our products lies beyond our control, we can only accept liability for the perfect standard quality at the time of delivery. Consequential losses will only be recognised if this was expressly agreed before use in writing, stating the warranted characteristics.



Chemetall (Schweiz) AG, Silostrasse 7, CH-5606 Dintikon
Phone: +41(0)56 616 90 30 Fax: +41(0)56 616 90 40
E-Mail: chemetall.schweiz@chemetall.com